

A41  
Power distribution


2 X10015



30<39  
0.5  
RT/GE

5 X04545

5 X4545



A117a  
Eject box

2 X4545

2 X04545

31E  
0.5  
BR

X3313

