


A7000
AGS transmission control unit


31 X70004
U_GETRPO
0.75
GN
5 X8532



| | L1 | L2 | L3 | L4 |
|---|----|----|----|----|
| P | 1 | 1 | 0 | 1 |
| R | 1 | 0 | 0 | 0 |
| N | 1 | 1 | 1 | 0 |
| D | 0 | 0 | 1 | 0 |
| 4 | 0 | 0 | 0 | 1 |
| 3 | 0 | 0 | 1 | 1 |
| 2 | 1 | 0 | 1 | 1 |

S8532
Gear position switch
0) Low (Off)
1) High (On)

1 L1 0.5 SW
3 L3 0.5 VI
4 L4 0.5 GE
2 L2 0.5 OR
X8532



A7000
AGS transmission control unit

34 14 4 24 X70004
31 L1 31 L3 31 L4 31 L2