



A42  
Rear power distribution box




3 X11017

30G1<102  
4.0  
RT/GN




4 X653



S55  
Passenger's lumbar support switch

2  
3  
5  
1  
6 X653  
LOBFM- 0.5 BR/GE  
LOBFPP 0.75 SW/WS  
OKBF 0.75 SW/BR  
UKBF 0.75 SW/BL

1 X739



M56a  
Drive for passenger's seat lumbar support

2 X739

LOBFPP 0.5 SW/WS

X1501

X1501

5  
3  
4 X1502



Y194  
Valve block, front right lumbar support

2 X1502

31 0.75 BR

31 0.5 BR

X018749

X018749

